

**T80900****1100w 19m Weldon Shank Auto-Reverse Tapping & Coe Drill Machine**

- Fully Mechanical tapping with automatic reversing controlled by crank motion
- Two-Mode gear-box: one mode for auto-reverse tapping and one mode for annular cutters and twist drills.

Motor	230V / 50Hz or 110V / 60Hz
Power	1100W
Annular Cutter Arbor	Set Screw Type, 19mm Weldon Shank
Annular Cutters	Dia. 35mm By 50mm Depth (1-3/8 × 2 in.)
Taps	12mm~19mm Magnetic Ashesion 40mm depth (1/2~3/4 in. × 1-9/16 in.)
Twist Drills	15mm × 80mm depth (9/16 × 3-9/64 in.)
Effective Stroke	Tapping: 40 mm (1-9/16 in.)
	Twist Drilling: 80mm (3-9/64 in.) Annular Cutters: 50mm (2 in.)
Magnetic Ashesion	15.000 N (3.372 lb-f)
N./ Weight kg(lbs.)	13.7 Kgs (30.8)
Drilling Mode	
No / Full Load r.p.m.	550 / 330
Tapping & Twist Drill Mode	
No / Full Load r.p.m.	150 / 90

Standard Accessories:

- * Tapping and drill chuck (clamping M12~M20 Taps, 8~15mm twist drills)
- * Annular cutter arbor (19mm Weldon shank)
- * 2.5mm hex key
- * 4mm hex key
- * Hook spanner wrench
- * Chip guard kit
- * Coolant tank kit
- * Safty chain

Optional Accessories:

- * Small Pange Tapping and drill chuck (clamping M4~M14 taps, 5~15 twist drills)

**T80903****1100W 1 Speed Magnetic Driling Machine**

Power Input	1100W	
No / Full Load RPM	620 / 350min	
Max. Capacity:	Dia. × Depth of Cut	35 mm × 50 mm
	Dia. × Depth of Twist Drill Bit	13 mm × 110 mm
	Dia. × Depth of Taps	NA
Magnetic Ashesion	15,000 N	
N./ Weight	12.6 Kg	

Standard Accessories:

- * Wrench M8
- * Hex. Key M2.5
- * Hex. Key M4
- * Chip Guard Kit
- * Coolant Tank Kit
- * Safety Chain

Optional Accessories:

- * Chuck Adaptor
- * 13mm Chuck & Key